

Service Measure

Sound System, Cruise, Alarms, Monitors

B65 209 04

04/30/2004

This Service Measure supersedes S.M. B65 209 04 **dated 03/24/2004**

Changes to this revision are identified [in blue text](#).

Subject

E39, E46, E53 with BM53 Radio, Navigation system and DSP or Harman/Kardon amplifier: Radio is switching from Stereo to Mono.

Complaint

In FM mode only the radio sound is switching from Stereo to Mono, fading in and out.

Cause

Software error in the BM53 Radio.

Measure

[On a customer complaint basis only, replace the BM53 radio.](#)

[Install a BM53 radio with the new software, P/N 65 12 4 135 562.](#)